

# Manhole Inspection Summary

# Manhole # S55E\_\_043MH

Printed On: 8/24/2009

Page 1 of 3

**Inspection**  Is Incomplete Rating: **3) Fair**

Record Plat: **55E** Node: **043** Status: **Found**

Insp Date: **5/18/09 3:12 PM**

Incomplete Comments

Crew: **REI**  
Inspector: **paulfry**  
Firm: **ATS**

**Location** Address: **3518 E LOMBARD ST**

Cross Street: **S CONKLING ST**

**Manhole** Type: **Terminal**

Location: **Roadway**

Ground Conditions: **Dry**

Prev. Rehab

Weather: **Dry**

Subject To Ponding: **None**

Comments

**Cover**

Shape: **Circular**

Diameter: **24** (in.) Length: **0** (in.) Dist A/B Grade: **0** (in.)

Type: **Sanitary**

Condition: **Sound**

Cover Material: **Cast Iron**

Properties:  Bolted  Vented  Water Tight  Water Tight Insert

**Frame**

Offset: **0** (in.)

Condition:  Sound  Cracked  Leaks

**Chimney / Frame Adjustment**

Exists Material: **Brick**

Parged Height: **4** (in.)

Condition:  Sound  Cracked  Root Intrusion  Loose Brick  **Deteriorated**

Infiltration:  None  Joint  Cracks  Mortar  Roots  Wall

**Corbel**

Material: **Brick**

Parged

Type: **Concentric/Eccentric**

Condition:  Sound  Cracked  Root Intrusion  Loose Brick  Deteriorated

Infiltration:  None  Joint  Cracks  Mortar  Roots  Wall

**Barrel**

Material: **Brick**

Parged

Shape: **Circular**

Diameter: **42** (in.) Length: **0** (in.)

Condition:  Sound  Cracked  Root Intrusion  Loose Brick  Deteriorated

Infiltration:  None  Joint  Cracks  Mortar  Roots  Wall

**Bench**

Exists Material:

Parged

Condition:  Sound  Cracked  Root Intrusion  Deteriorated  Leaks  Debris

**Channel**

Material: **Brick**

Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth: **0**

Condition:  Sound  Cracked  Root Intrusion  Deteriorated  Leaks  Debris

**Steps**

Count: **0** Missing: **4**  **Corroded**

**Surcharge**

Evidence Of Surcharge Depth: **0** (ft.)  Active Surcharge Present

Location View



Top View



MISC.



CUT OFF COVER TO GAIN ACCESS;  
PAVEMENT MARKED

Defect 2



CORRODED MISSING STEPS

Defect 1



DETERIORATED CHIMNEY BRICKS

# Manhole Inspection Summary

Manhole # S55E\_\_043MH

Printed On: 8/24/2009

Page 3 of 3

8 in. Circular Gravity Sewer  
Pipe Out @ 12 O'Clock

12 O'Clock Outflow



Pipe Height: **8.4** (in.) Rod and Bar (Angled)

Pipe Material: **Clay**  Pipe Lined

Invert Depth: **6.98** (ft.) Flow Characteristics: **None**

Deposits:  None  Mud  Sludge  Debris  Grease

Silt Depth: **0** (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**

Possible Illicit Connection